



**RETAIL FOOD PROTECTION - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>DIAMOND WOK</b>				REINSPECTION <b>Next Routine</b>	INSPECTOR <b>John Ramos</b>	DATE <b>9/28/2015</b>
LOCATION <b>13677 FOOTHILL BL H, FONTANA, CA 92336</b>				PERMIT <b>4/30/2015</b>	IDENTIFIER: None	
TIME IN <b>2:41 PM</b>	TIME OUT <b>2:56 PM</b>	FACILITY ID <b>FA0003186</b>	RELATED ID <b>PR0003261</b>	PE <b>1621</b>	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED	

**RETAIL FOOD PROTECTION - Public Eating PI (25-99 Seats)**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

**16K994 Reinspection**

Comply by: 9/28/2015  
Complied on 9/28/2015  
Reference - HSC

**Inspector Comments:** Reinspection conducted to determine the status of the repairs for the drain lines for the 3 compartment sink, which may have resulted in closure if not completed today.

Observed drain lines under the 3 compartment sink have been repaired, and is in full use.

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Reinspection performed to determine the status and compliance of the drain lines for the 3 compartment sink.

The drain lines have been repaired and the 3 compartment sink is in full working order.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0