






Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|--|--|--------------------------|---|---------------------------------------|
| FACILITY NAME PENNY'S DINER/OAK TREE | | DATE 6/25/2015 | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 2/28/2016 |
| LOCATION 35450 YERMO RD, YERMO, CA 92398 | | | INSPECTOR Michelle Saltis | |
| MAILING ADDRESS 8080 E CENTRAL STE 180, WICHITA KS 67206 | | | IDENTIFIER: Pool | |
| TIME IN 3:24 PM | | | SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION | |
| TIME OUT 3:43 PM | | | RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED | |
| FACILITY ID FA0011420 | | | ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN | |
| RELATED ID PR0014043 | | | | |
| PE 3620 | | | | |

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (°F) | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | 29 |
| volume (gal) | 10,500 |
| area (sq ft) | 342 |
| occupancy | 17 |

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

| | | |
|---------------------|--------------------------------|--|
| POINTS NA | Compliance Date: Not Specified | Inspector Comments: Facility is now in compliance with gate/fencing issues and chlorine levels. Facility permit is now reinstated and may reopen. |
| | Not In Compliance | |
| | Violation Reference - HSC | |

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

| | | |
|---------------------|--------------------------------|--|
| POINTS NA | Compliance Date: Not Specified | Inspector Comments: A reinspection was conducted today, 6/25/15 to follow up on compliance of the pool fencing, gate and chlorine levels. Observed gate to self close. Observed fencing on bottom repaired. Observed chlorine level at 9.4ppm. |
| | Not In Compliance | |
| | Violation Reference - HSC | |

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Cyanuric acid is at or above 111ppm.

Signature(s) of Acknowledgement

NAME: marie Escobosa
TITLE:

Total # of Images: 0