



**COMMUNITY ENVIRONMENTAL HEALTH PROGRAM  
RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT**

[www.sbcounty.gov/dph/dehs](http://www.sbcounty.gov/dph/dehs)

**(800) 442-2283**

FACILITY NAME <b>WOODSONG APARTMENTS</b>				DATE <b>2/23/2015</b>	SIGNATURE	
LOCATION <b>8255 VINEYARD AV, RANCHO CUCAMONGA, CA 91730</b>					REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION
MAILING ADDRESS <b>325 W 3RD ST SAN DIMAS, CA 91773</b>				REHS <b>Bennetta Betbadal</b>		
FA # <b>FA0006559</b>	PR # <b>Not Specified</b>	SR # <b>SR0067017</b>	CO # <b>Not Specified</b>	PE <b>3716</b>	PROGRAM IDENTIFIER: <b>None</b>	
TIME IN <b>2:30 PM</b>	TIME OUT <b>2:54 PM</b>	CONTACT <b>Not Captured</b>			SERVICE: <b>025 - PLAN REVIEW</b>	
					RESULT: <b>01 - CORRECTIVE ACTION NOT REQUIRED</b>	
					ACTION: <b>56 - UPDATE TO APPROVED PLANS</b>	

**RECREATIONAL HEALTH PLAN CHECK - Plnck Pool Minor Remodel - all**

**37K980 Plans - Plan Review Approved**

Compliance Date: **Not Specified**

Not In Compliance

Violation Reference - **HSC**

Inspector Comments: Plan is approved for minor remodel of the spa.

Scope of work consist of new trim tiles, waterline tiles, new handrails, depth markers and no diving sings and replaster.

Violation Description: Plans have been approved and this correction sheet is a part of the approved plans.

**Overall Inspection Comments**

Spa Capacity: 1500 gallons

Flow rate: 50 gpm

Circulation pump: Pentair 1.5 Hp 99 gpm

Booster pump: Pentair 1.5 HP 99 gpm

Filter: Pentair Triton TR100c 98 gpm

Maid drain suction lines and equalizer line: 2" at 8 fps is 84 gpm

Return line: 2" at 10 fps is 105 gpm

**Photo Attachments:**

No Photo Attachments