



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME UNIVERSITY PALMS APTS		DATE 5/5/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 25356 COLE ST, LOMA LINDA, CA 92354			INSPECTOR Veronica Vazquez	
MAILING ADDRESS 25356 COLE ST, LOMA LINDA, CA 92354			IDENTIFIER: None	
TIME IN 4:35 PM	TIME OUT 4:48 PM	FACILITY ID FA0008687	RELATED ID CO0049984	PE 3620
			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed facility closed with pad lock. Observed closure sign posted 2-19-15. Contact the County of San Bernardino, Division of Environmental Health Services (DEHS) when compliance is reached. Maintain pool closed until re-opened by DEHS inspector.
	Not In Compliance Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

36K595 Construction – Construction or alterations

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Submit plans to DEHS prior to any construction/remodeling begins. Observed deck in pool torn and trenches with pipes exposed.
	Not In Compliance Violation Reference - CCR - 3103B	

Violation Description: A person proposing to construct, renovate or alter a pool, ancillary facilities or equipment and appurtenances shall submit plans and specifications detailing compliance with this chapter to the enforcing agent for review and written approval prior to commencing construction and shall first be cleared by the enforcing agent before substitution if not an exact duplicate of the units being changed or replaced.

Overall Inspection Comments

Call Veronica Vazquez at (800) 442-2283 with questions.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0