



Public Health

Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME ALTA LOMA HIGH SCHOOL		DATE 8/14/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701			INSPECTOR Robert Adams	
MAILING ADDRESS 276 N SECOND AVE UPLAND, CA 91786			IDENTIFIER: None	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 126 - PLAN CHECK FIELD INSPECTION	
TIME IN 3:05 PM	TIME OUT 4:00 PM	FACILITY ID FA0006436	RELATED ID SR0065247	PE 3712
			RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU	
			ACTION: 03 - REINSPECTION REQUIRED	

RECREATIONAL HEALTH PLAN CHECK - PInCk Pool New 1,000-Up SqFt

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K064 Enclosure - General - 4"

Compliance Date: Not Specified

Not In Compliance

Reference - CCR 24 - 3118B(a)

Inspector Comments: Observed portions of a new fencing enclosure with large gaps under it. The gaps are greater than 4 inches. Ensure no gaps greater than 4 inch exist for this pool enclosure.

Description: Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a four (4) inch diameter sphere.

37K067 Enclosure - General - Climb

Compliance Date: Not Specified

Not In Compliance

Reference - CCR 24 - 3118B.3

Inspector Comments: Observed portion of fencing on the east side of the enclosure which was climbable. The contractor stated it was going to be completed by Monday with a piece of permanent mesh to obstruct climbing.

Description: The enclosure shall be designed and constructed so that it cannot be readily climbed by small children. Horizontal and diagonal member designs, which might serve as a ladder for small children, are prohibited. Horizontal members shall be spaced at least 48 inches apart.

37K246 Safety - General - Sign

Compliance Date: Not Specified

Not In Compliance

Reference - CCR 22 - 65539

Inspector Comments: See below.

Description: Post safety signs and supply safety equipment so that they will be clearly visible and readily available to the pool.

37K247 Safety - General - Signs

Compliance Date: Not Specified

Not In Compliance

Reference - CCR 22 - 65539

Inspector Comments:
<http://www.sbcounty.gov/uploads/dph/dehs/Depts/EnvironmentalHealth/FormsPublications/RequiredSignsforPools.pdf>

See the above mentioned link for more detailed information on required pool signs.

Description: Post the following safety signs: a) "No lifeguard on duty. Children under the age of 14 should not use pool without an adult in attendance." b) Diagrammatic illustration of artificial respiration. c) Emergency telephone numbers.

37K517 Enclosure - General - Bottom

Compliance Date: Not Specified

Not In Compliance

Reference - Reference Number - SBC Policy

Inspector Comments: Observed bottom of newly installed fencing over dirt. Ensure the fencing is over a surface as prescribed below. Contractor discussed installing a mow curb to ensure the fencing is no more than 4 inches from the mow curb.

Description: Pool enclosures to be constructed over hard or permanent material (concrete decking, packed gravel, or equivalent).

Overall Inspection Comments

Ensure all pipes within the pool equipment room are properly labeled to show the directional flow.

Reinspection requested for Monday 8-17-15. Inspector to check with Supervisor to see if staff are available for that date.

Back up date set for 8-21-15.



Public Health
Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME ALTA LOMA HIGH SCHOOL	DATE 8/14/2015
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701	INSPECTOR Robert Adams

Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0