



**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

|   |                            |                                 |  |  |
|---|----------------------------|---------------------------------|--|--|
| FACILITY NAME<br><b>LAKE ARROWHEAD COUNTRY CLUB</b>             |                            | DATE<br><b>8/25/2015</b>        | REINSPECTION DATE<br><b>Not Specified</b>        | PERMIT EXPIRATION<br><b>12/31/2015</b> |
| LOCATION<br><b>250 GOLF COURSE RD, LAKE ARROWHEAD, CA 92352</b> |                            |                                 | INSPECTOR<br><b>Yvette Velasco</b>               |  |
| MAILING ADDRESS<br><b>PO BOX 670, LAKE ARROWHEAD CA 92352</b>   |                            |                                 | IDENTIFIER: Pool                                 |  |
| TIME IN<br><b>4:34 PM</b>                                       | TIME OUT<br><b>5:02 PM</b> | FACILITY ID<br><b>FA0007771</b> | RELATED ID<br><b>PR0013888</b>                   | PE<br><b>3620</b>                      |
|   |                            |                                 | SERVICE: 001 - INSPECTION - ROUTINE              |  |
|   |                            |                                 | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE |  |
|   |                            |                                 | ACTION: 01 - NO FURTHER ACTION REQUIRED          |  |

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.




**96**

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

|                   |
|-------------------|
| Ideal             |
| In Compliance     |
| Not in Compliance |



|                     |         |
|---------------------|---------|
| temperature (°F)    | 80.0    |
| observed flow (gpm) | No Data |
| required flow (gpm) | 166     |
| volume (gal)        | 80,000  |
| area (sq ft)        | No Data |
| occupancy           | 90      |

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:  
1. Meet the latest ANSI/APSP-16 performance standard  
2. Be rated for the maximum designed flow-rate of the pump  
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K504 Water Quality – Non-Critical – Disinfectant level low**

|                           |                                   |  |
|---------------------------|-----------------------------------|--|
| <b>POINTS</b><br><b>1</b> | Compliance Date: Not Specified    | Inspector Comments: Observed the free chlorine at 1.4ppm.                        |
|                           | Not In Compliance                 | Ensure to maintain free chlorine in the pool at 2.0-10.0ppm, with cyanuric acid. |
|                           | Violation Reference - HSC - 65529 |  |

**Violation Description:** The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

**36K546 Equipment – Non-Critical - Water treatment system operation**

|                           |                                   |  |
|---------------------------|-----------------------------------|--|
| <b>POINTS</b><br><b>1</b> | Compliance Date: Not Specified    | Inspector Comments: No access to the pump room was provided due to a lack of pool staff on site. The person in charge stated that the pool is now only open on weekends. |
|                           | Not In Compliance                 | Ensure to allow access to the pump room for inspections.   |
|                           | Violation Reference - HSC - 65525 |  |

**Violation Description:** The pool operator shall operate pumps, filters, disinfectant and chemical feeders, flow indicators, gauges, recirculation systems, disinfection systems, and all parts of the water treatment system whenever the public pool is available for use, and at such additional times and periods as may be necessary to maintain clean pool water, clear pool water, and the disinfection standards required in section 65529 [Health and Safety Code].



## Public Health

### Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)

### RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

|   |                                    |
|---|------------------------------------|
| FACILITY NAME<br><b>LAKE ARROWHEAD COUNTRY CLUB</b>             | DATE<br><b>8/25/2015</b>           |
| LOCATION<br><b>250 GOLF COURSE RD, LAKE ARROWHEAD, CA 92352</b> | INSPECTOR<br><b>Yvette Velasco</b> |

#### IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

#### 36K572 Maintenance – Pool shell cleanliness; slime and algae

|                           |                                   |   |
|---------------------------|-----------------------------------|---|
| <b>POINTS</b><br><b>1</b> | Compliance Date: Not Specified    | Inspector Comments: Observed build-up dirt in the pool. |
|                           | Not In Compliance                 |   |
|                           | Violation Reference - HSC - 65533 | Ensure to clean and maintain the pool shell.            |

**Violation Description:** (a) The pool operator shall maintain clean pool water while the public pool is in use. The pool operator shall not allow debris, including, but not limited to, floating scum, sputum, trash, or leaves, to accumulate in the public pool. The pool operator shall ensure that water levels are maintained and operated to remove such material continuously through the pool skimming system in accordance with section 3136B, Title 24, California Code of Regulations.

(b) The pool operator shall clean the bottom, sides, and other surfaces of the public pool as often as necessary to keep the bottom, sides, and public pool surfaces clean and free of slime and algae.

#### 36K597 Construction - Pool shell tiles and surface

|                           |                                   |   |
|---------------------------|-----------------------------------|---|
| <b>POINTS</b><br><b>1</b> | Compliance Date: Not Specified    | Inspector Comments: Observed the pool finish color of the pool is blue.                           |
|                           | Not In Compliance                 |   |
|                           | Violation Reference - CCR - 3108B | Ensure to maintain the pool finish color white except for the specified portions specified below. |

**Violation Description:** The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing and cleaning procedures. The interior pool finish shall completely line the pool to the tile lines, coping, or cantilevered deck.

The finish color shall be white except for the following which shall be of contrasting color:

1. Lane and other required pool markings described in Section 3110B of the California Code of Regulations; and
2. The top surface edges of benches in spa pools; and
3. The edge of pool steps; and
4. Tiles installed at the waterline; and
5. Tiles installed at the 4 1/2-foot (1372 mm) depth line.

#### Overall Inspection Comments

No summary comments have been made for this inspection.

#### Signature(s) of Acknowledgement

NAME: Lya Silva  
TITLE:

Total # of Images: 0