



## Public Health

### Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)

### RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME RED TILE INN		DATE 6/23/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 1311 R V CENTER DR, COLTON, CA 92324			INSPECTOR Bennetta Betbadal	
MAILING ADDRESS 1200 ARIZONA B15 REDLANDS, CA 92374			IDENTIFIER: None	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 025 - PLAN REVIEW	
TIME IN 3:50 PM	TIME OUT 4:26 PM	FACILITY ID FA0008664	RELATED ID SR0068890	PE 3716
RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED				
ACTION: 55 - PLANS APPROVED				

## RECREATIONAL HEALTH PLAN CHECK - Plnck Pool Minor Remodel - all

### IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

### 37K980 Plans - Plan Review Approved

Compliance Date: Not Specified

Not In Compliance

Reference - HSC

Inspector Comments: Plan is approved for splitting the main drain and booster suction lines for spa and replaster.

Description: Plans have been approved and this correction sheet is a part of the approved plans.

### Overall Inspection Comments

Pump: Pentair Inteliflo SVRS

Main drain Suction line: 1.5" with 51 gpm at 8 fps

Booster suction: 2" with 84 gpm at 8 fps

### Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0