



**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME SPRING VALLEY LAKE COUNTRY CLUB		DATE 8/11/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2015
LOCATION 13229 SPRING VALLEY LAKE PKWY, VICTORVILLE, CA 92392			INSPECTOR Melissa Nano	
MAILING ADDRESS 7070 SVL BOX, VICTORVILLE CA 92392			IDENTIFIER: Pool	
TIME IN 3:38 PM	TIME OUT 4:20 PM	FACILITY ID FA0006828	RELATED ID PR0014766	PE 3620
			SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**96**  
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	338
volume (gal)	160,000
area (sq ft)	1,800
occupancy	150

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K508 Water Quality – Non-Critical – Water pH 7.2 to 7.8**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b>
	Not In Compliance	Maintain pH between 7.2. and 7.8.
	Violation Reference - HSC - 65530	Observed pH at 7.0.

**Violation Description:** The pool operator shall maintain public pool water at pH 7.2 to 7.8.

**36K556 Equipment – Plumbing labeled**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b>
	Not In Compliance	Label and indicate, using arrows, the direction of flow of water onto recirculation piping.
	Violation Reference - CCR 24 - 3120B	Observed missing.

**Violation Description:** The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area. Where the recirculation equipment for more than one pool is located on site, the equipment shall be marked as to which pool the system serves. Valves and plumbing lines shall be labeled clearly with the source or destination descriptions.

**36K562 Skimmers - Pool skimming systems**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b>
	Not In Compliance	Obtain weir gates for two skimmers systems to properly skim water.
	Violation Reference - CCR - 3136B	Observed missing.

**Violation Description:** The pool shall be equipped with one or more skimming methods to provide continuous skimming of the pool water and shall be capable of continually withdrawing not less than 100 percent of the flow rate. Each surface skimmer shall comply with the requirements in accordance with section 3136B, Title 24, California Code of Regulations.



**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>SPRING VALLEY LAKE COUNTRY CLUB</b>	DATE <b>8/11/2015</b>
LOCATION <b>13229 SPRING VALLEY LAKE PKWY, VICTORVILLE, CA 92392</b>	INSPECTOR <b>Melissa Nano</b>

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K582 Maintenance - Public pool site maintenance**

**POINTS**  
**1**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC - 65535

**Inspector Comments:**  
 Repair hand rail at entry entry steps near front entrance.  
 Observed loose.  
 \_\_\_\_\_  
 Repair concrete decking throughout perimeter of pool.  
 Observed several cracked cement creating significant small chips of cement.  
 \_\_\_\_\_  
 Clean and maintain pump room to rid of D.E. powder on floor.  
 Observed significant amounts of dried D.E. powder.  
 \_\_\_\_\_

**Violation Description:** The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

**Overall Inspection Comments**

If there are any questions, please contact Environmental Health Services or Melissa Nano at (800) 442-2283.

**Signature(s) of Acknowledgement**

NAME: Wayne B.  
 TITLE:

Total # of Images: 0