





**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME PARC PLACE		DATE 8/21/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 8/31/2014
LOCATION 13133 LE PARC, CHINO HILLS, CA 91709			INSPECTOR Casey Salazar	
MAILING ADDRESS PO BOX 5022, UPLAND CA 91785-5022			IDENTIFIER: Spa	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 2:26 PM	TIME OUT 2:38 PM	FACILITY ID FA0003131	RELATED ID PR0015479	PE 3623
			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	33
volume (gal)	1,000
area (sq ft)	50
occupancy	5

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Spa has been opened by Environmental Health.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> A follow up inspection was conducted regarding high chlorine levels observed during last routine inspection. Free chlorine levels were measured at 10 ppm.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Spa opened

**Signature(s) of Acknowledgement**

NAME: Signature not available  
 TITLE:

Total # of Images: 0