



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|--|-----------------------------|---------------------------------|--|-------------------|
| FACILITY NAME CHINO HILLS HIGH SCHOOL | | DATE 9/4/2015 | REINSPECTION DATE Next Routine | PERMIT EXPIRATION |
| LOCATION 16150 POMONA RINCON RD, CHINO HILLS, CA 91709 | | | INSPECTOR Casey Salazar | |
| MAILING ADDRESS 5130 RIVERSIDE DR, CHINO CA 91710 | | | IDENTIFIER: None | |
| <input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT | | | SERVICE: 001 - INSPECTION - ROUTINE | |
| TIME IN 11:19 AM | TIME OUT 12:06 PM | FACILITY ID FA0010509 | RELATED ID PR0035477 | PE 3603 |
| | | | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE | |
| | | | ACTION: 01 - NO FURTHER ACTION REQUIRED | |

RECREATIONAL HEALTH - Public School Pool / Spa

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.




99

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (°F) | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | No Data |
| volume (gal) | No Data |
| area (sq ft) | No Data |
| occupancy | No Data |

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K582 Maintenance - Public pool site maintenance

| | | |
|---------------------------|-----------------------------------|---|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Observed throw ropes on both life rings deteriorating from sun exposure. Replace throw rope. Operator replaced one throw rope at time of inspection and has placed orders for 2 more. |
| | Not In Compliance | |
| | Violation Reference - HSC - 65535 | |

Violation Description: The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

Overall Inspection Comments

Pool inspection conducted

Flow rate: 1385 GPM

Signature(s) of Acknowledgement

NAME: Floyd
TITLE: PIC

Total # of Images: 0