



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>PARK VILLAGE APARTMENTS</b>		REINSPECTION DATE <b>Not Specified</b>		INSPECTOR <b>Patrick Baccari</b>	DATE <b>9/22/2015</b>
LOCATION <b>10033 JUNIPER, FONTANA, CA 92335</b>		PERMIT EXPIRATION <b>5/31/2016</b>		IDENTIFIER: Spa SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	
TIME IN <b>1:30 PM</b>	TIME OUT <b>1:58 PM</b>	FACILITY ID <b>FA0008618</b>	RELATED ID <b>PR0014386</b>	PE <b>3623</b>	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**90**  
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	40
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K502 Water Quality - Critical – Disinfectant level** **⚠ CRITICAL ⚠**

<b>POINTS</b> <b>5</b>	Compliance Date: <b>Not Specified</b>	<b>Inspector Comments:</b> Observed spa water tested High for chlorine, 11.0 ppm was entered on report.
	<b>Not In Compliance</b>	Maintain free available chlorine level at 2 - 10.0 ppm.
	Violation Reference - <b>HSC - 65529</b>	Spa is currently closed by operator. Pool area was opened for inspection purposes at this time.
		Adjust free available chlorine level to 2 - 10.0 ppm prior to opening for use.

**Violation Description:** The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

A spray ground and water features with an ultraviolet light disinfection system shall be disinfected continuously at a minimum of 40 mJ/cm<sup>2</sup> by the ultraviolet light disinfection units while the spray ground and water features are in use. If the ultraviolet dosage rate drops below 40 mJ/cm<sup>2</sup> the operator shall close the spray ground and water features.

**36K506 Water Quality - Critical – Water pH 7.2 to 7.8** **⚠ CRITICAL ⚠**

<b>POINTS</b> <b>5</b>	Compliance Date: <b>Not Specified</b>	<b>Inspector Comments:</b> Observed Ph for spa water tested High, 8.2 was entered on report.
	<b>Not In Compliance</b>	Maintain Ph at 7.2 - 7.8
	Violation Reference - <b>HSC - 65530</b>	Pool is currently closed by operator. Pool area was opened for inspection purposes at this time.
		Adjust Ph to 7.2 - 7.8 prior to opening for use.

**Violation Description:** The pool operator shall maintain public pool water at pH 7.2 to 7.8.

**Overall Inspection Comments**

No summary comments have been made for this inspection.



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME PARK VILLAGE APARTMENTS	DATE 9/22/2015
LOCATION 10033 JUNIPER , FONTANA, CA 92335	INSPECTOR Patrick Baccari

**Signature(s) of Acknowledgement**

NAME:

TITLE:

Total # of Images: 0