



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|---|----------------------------|--|---------------------------------------|--------------------------|
| FACILITY NAME CITRUS VALLEY HIGH SCHOOL | | REINSPECTION DATE Next Routine | INSPECTOR Marilyn Krichbaum | DATE 11/6/2015 |
| LOCATION 800 W PIONEER AV, REDLANDS, CA 92373 | | PERMIT EXPIRATION | IDENTIFIER: None | |
| TIME IN 7:55 AM | TIME OUT 8:45 AM | FACILITY ID FA0020739 | RELATED ID PR0027910 | PE 3603 |
| | | SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED | | |

RECREATIONAL HEALTH - Public School Pool / Spa

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).




98

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|---------|
| temperature (°F) | No Data |
| observed flow (gpm) | 862 |
| required flow (gpm) | 840 |
| volume (gal) | 300,000 |
| area (sq ft) | No Data |
| occupancy | No Data |

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K527 Safety – Safety signs

| | | |
|---------------------------|--|---|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Replace the following missing pool signs: Keep gate closed. Name and address of facility. Nearest emergency services telephone number in addition to the 911 sign. Replace the warning no lifeguard on duty sign, the wording has changed. |
| | Not In Compliance | |
| | Violation Reference - CCR - 3120B | |

Violation Description: All signs shall have clearly legible letters or numbers not less than 4 inches high, unless otherwise required, affixed to a wall, pole, gate or similar permanent structure in a location visible to all pool users. The following shall be posted:

- a) Maximum number of pool users permitted for each pool.
- b) ""NO DIVING"" at pools with a maximum water depth of 6 feet or less.
- c) Where no lifeguard service is provided, a warning sign shall be posted stating, ""WARNING: NO LIFEGUARD ON DUTY."" The sign also shall state in letters at least 1 inch high, ""Children under the age of 14 shall not use pool without a parent or adult guardian in attendance.""
- d) An illustrated diagram with text at least 1/4 inch high of artificial respiration and CPR procedures.
- e) The emergency telephone number 911 with numbers not less than 4 inches (102mm), the number of the nearest emergency services and the name and street address of the pool facility with numbers and text not less than 1 inch (25 mm) shall be posted.
- f) A warning sign for spa pools with ""CAUTION"" language.
- g) Where pools were constructed for which lighting was not required, a sign shall be posted at each pool entrance on the outside of the gate(s) stating, ""NO USE OF POOL ALLOWED AFTER DARK.""
- h) A sign shall be posted on the exterior side of gates and doors leading into the pool enclosure area stating, ""KEEP GATE CLOSED"" or ""KEEP DOOR CLOSED"".
- i) A sign in letters at least 1 inch high and in a language or diagram that is clearly stated shall be posted at the entrance area of a public pool which states that persons having currently active diarrhea or who have had active diarrhea within the previous 14 days shall not be allowed to enter the pool water.
- j) A sign in letters at least 1 inch high shall be posted that describes the requirements for wave pools.
- k) A sign shall be posted at each spray ground and be visible from any part of the spray ground that states, ""CAUTION: WATER IS RECIRCULATED. DO NOT DRINK.""

36K582 Maintenance - Public pool site maintenance

| | | |
|---------------------------|--|--|
| POINTS 1 | Compliance Date: Not Specified | Inspector Comments: Secure the loose handrails. Repair/replace the nonfunctioning hand dryer in the girl's restroom. |
| | Not In Compliance | |
| | Violation Reference - HSC - 65535 | |

Violation Description: The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | |
|--|--------------------------------|
| FACILITY NAME CITRUS VALLEY HIGH SCHOOL | DATE 11/6/2015 |
| LOCATION 800 W PIONEER AV, REDLANDS, CA 92373 | INSPECTOR Marilyn Krichbaum |

Overall Inspection Comments

Recommend another rescue pole and life ring for the other side of this large pool.

Signature(s) of Acknowledgement

NAME: discussed with employee
TITLE:

Total # of Images: 0