



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME UNIVERSITY PALMS APTS		DATE 3/12/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 10/31/2014
LOCATION 25356 COLE ST, LOMA LINDA, CA 92354			INSPECTOR Veronica Vazquez	
MAILING ADDRESS PO BOX 60117, SAN DIEGO CA 92166			IDENTIFIER: Pool	
TIME IN 2:10 PM			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME OUT 2:30 PM			RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU	
FACILITY ID FA0008687			ACTION: 13 - PERMIT SUSPENDE / FACILITY CLOSED	
RELATED ID PR0014101			PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	91
volume (gal)	33,000
area (sq ft)	800
occupancy	40

36K995 Permit - Suspension

CRITICAL

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Pool must remain closed until sewage issue is eliminated in apartment complex and pool reparation is completed. Observed no sewage back up at time of inspection.
	Not In Compliance	
	Violation Reference - HSC	

Violation Description: Violation(s) observed pose an immediate threat to public health and safety. The health permit to operate is hereby suspended and the pool/spa ordered closed until the listed violation(s) have been corrected and verified by Environmental Health Services (EHS). The facility is to remain closed until permission from EHS is given. Contact your inspector at your local office to schedule a reinspection to reinstate the health permit. The facility is posted closed; do not move, hide, or remove the sign. Reopening of the pool/spa without the approval by EHS, may result in an hourly billable Professional Services fee.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Observed pool gate locked and closure sign posted. Observed pool water green and with heavy debris build up. Observed deck area around pool broken and pipes visible. Contacted manager that states apartment complex had a sewage back up issue and all piping for sewage will be replaced. Contact Division of Environmental Health Services prior to reopening pool. Pool water must be in a sanitary state.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

36K476 Decking - Requirements

POINTS 2	Compliance Date: Not Specified	Inspector Comments: Provide deck area. Observed broken deck area and pipes visible.
	Not In Compliance	
	Violation Reference - CCR - 3114B	

Violation Description: A minimum continuous and unobstructed 4-foot wide slip resistant, cleanable, nonabrasive deck area of concrete or like material shall be provided flush with the top of the pool coping extending completely around the pool, and the deck area shall further extend 4 feet both sides and rear of any diving board, fixed disabled access assistance device or slide and their appurtenances. Deck shall be maintained in good repair.

Overall Inspection Comments

Call Veronica Vazquez at (800) 442-2283 with questions.

Signature(s) of Acknowledgement

NAME:
TITLE:

Photo Attachments:
No Photo Attachments