




**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>RAMADA INN</b>		DATE <b>9/10/2015</b>	REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>12/31/2015</b>
LOCATION <b>1511 E MAIN ST, BARSTOW, CA 92311</b>			INSPECTOR <b>Michelle Saltis</b>	
MAILING ADDRESS <b>1511 E MAIN ST, BARSTOW CA 92311</b>			IDENTIFIER: Spa	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN <b>12:32 PM</b>	TIME OUT <b>12:59 PM</b>	FACILITY ID <b>FA0006202</b>	RELATED ID <b>PR0014854</b>	PE <b>3623</b>
			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

<b>Ideal</b>
<b>In Compliance</b>
<b>Not in Compliance</b>



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	27
volume (gal)	1,700
area (sq ft)	86
occupancy	8

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Facility is now in compliance with the main drain cover.  Spa permit is hereby reinstated and facility may reopen spa.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> A reinspection was conducted today to follow up on compliance of the main drain cover.  Observed main cover replaced and in good condition. Observed water clarity clear.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Spa permit is reinstated and facility may reopen spa.

**Signature(s) of Acknowledgement**

NAME: julie danielson  
TITLE: front desk manager

Total # of Images: 0