



**Public Health**  
**Environmental Health Services**



www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME WOODSIDE TOWNHOMES			DATE 8/6/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 8692 9TH ST, RANCHO CUCAMONGA, CA 91730			INSPECTOR Shannon Johnson		
MAILING ADDRESS 195 N EUCLID AV STE 100, UPLAND CA 91786			IDENTIFIER: Spa		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION		
TIME IN 9:27 AM	TIME OUT 9:48 AM	FACILITY ID FA0016373	RELATED ID PR0021803	PE 3623	RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE
			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN		

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	74
volume (gal)	2,223
area (sq ft)	114
occupancy	11

**IMPORTANT: Replacement of Suction Outlet Covers**

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

**Inspector Comments:** At this time, the drain covers to this spa were observed to all be in good repair.

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

**Inspector Comments:** On 8-4-15, this spa was closed by a pool aide from this department due to a damaged AB1020 drain cover.

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Correct any other noted violations from the last routine inspection report.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:

Total # of Images: 0