



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>RANCHO CUCAMONGA HIGH SCHOOL</b>			REINSPECTION DATE <b>Next Routine</b>	INSPECTOR <b>Dior Porter</b>	DATE <b>9/23/2015</b>
LOCATION <b>11801 LARK DR, RANCHO CUCAMONGA, CA 91701</b>			PERMIT EXPIRATION	IDENTIFIER: Pool SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	
TIME IN <b>2:16 PM</b>	TIME OUT <b>3:20 PM</b>	FACILITY ID <b>FA0001702</b>	RELATED ID <b>PR0013691</b>	PE <b>3603</b>	

**RECREATIONAL HEALTH - Public School Pool / Spa**



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

**98**  
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	1,235
volume (gal)	444,703
area (sq ft)	6,300
occupancy	315

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K508 Water Quality – Non-Critical – Water pH 7.2 to 7.8**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed pH of 7.1. Maintain pH at 7.2 - 7.8.
	Not In Compliance	
	Violation Reference - HSC - 65530	

**Violation Description:** The pool operator shall maintain public pool water at pH 7.2 to 7.8.

**36K566 Lighting – Requirements**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed 2 non-functional lights at the south and west area of the pool. Repair the lights.
	Not In Compliance	
	Violation Reference - CCR - 3115B	

**Violation Description:** Pools shall have underwater and deck lighting such that lifeguards or other persons may observe, without interference from direct and reflected glare from the lighting sources, every part of the underwater area and pool surface, all diving boards or other pool appurtenances.

**Overall Inspection Comments**

flow rate: 1528 GPM

**Signature(s) of Acknowledgement**

NAME:  
TITLE:



**Public Health**  
Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)  
[www.SBCounty.gov/dph/dehs](http://www.SBCounty.gov/dph/dehs)

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME RANCHO CUCAMONGA HIGH SCHOOL	DATE 9/23/2015
LOCATION 11801 LARK DR, RANCHO CUCAMONGA, CA 91701	INSPECTOR Dior Porter

**Total # of Images: 0**