



## Public Health

### Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)

### RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME HOLIDAY INN VICTORVILLE		DATE 4/14/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 15494 PALMDALE RD, VICTORVILLE, CA 92392			INSPECTOR Bennetta Betbadal	
MAILING ADDRESS 20401 VALLEY BL # 202 WALNUT, CA 91789			IDENTIFIER: None	
TIME IN 8:00 AM			SERVICE: 025 - PLAN REVIEW	
TIME OUT 9:58 AM			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
FACILITY ID FA0004497			ACTION: 55 - PLANS APPROVED	
RELATED ID SR0067862			PE 3711	

## RECREATIONAL HEALTH PLAN CHECK - PInCk Pool Major Remodel 0-999 SqFt

### 37K980 Plans - Plan Review Approved

Compliance Date: Not Specified

Not In Compliance

Reference - HSC

Inspector Comments: Plan is approved for remodel of existing pool.

Scope of work consist of:

1. Raise the 8' depth of pool to a new 4'.
2. Add a manual ADA lift (Model IGAT-180) Oasis Custom Pools to supply and install.
3. Resurface the remaining inside of pool with White Marbled Plaster. Replace coping with new White safety Grip Coping.
4. Install new feet, meter and NO DIVING tile both inside tile border and deck top.
5. Test pump lines prior to starting to make sure they are leak free.  
Note: Any leak repair needed will be discussed and repaired at an additional cost.
6. Replace all ladders and handrails with new stainless steel SR Smith ladders and 3 bend handrails.
7. Test all pool lighting to make sure it is in working order and upgrade each outlet to a new LED multi-color light unit.
8. Remove old skimmers and replace with new skimmers, split main drains.
9. Start up pool and test for any problems.
10. Install new pool heater, Heater to be supplied by Owner.
11. Install new filter Pentair THS Horizontal Sand up to 203 gpm
12. New pump Pentair D series DMJ3-172 160 gpm
13. New automatic chemical controller Pentair AK 600
14. new auto fill Pentair T40-F
- 15- new chlorine feeder R17107 300-29X

Description: Plans have been approved and this correction sheet is a part of the approved plans.

### Overall Inspection Comments

Existing showers, restrooms, are subject to filed inspection and approval.

Existing fence and gates and decking are subject to filed inspection and approval.

Pool surface area: 252 lf

Pool capacity before remodel: 90,800 gallons

Pool capacity after remodel: 57,820 gallons

New flow rate: 160 gpm

Main drain: 4" at 6 fps ih 238 gpm

Skimmer suction lines: 2" at 6 fps 63 gpm with 7 skimmers

Drain covers: Waterways 640-1900V 10.2"

- 1- Equalizer lines should have approved covers.
- 2- Call for pre-plaster inspection. during pre-plaster inspection main drain's split shall be exposed to verify the even "T" split.
- 3- During pre-plaster inspection fence and gates shall be completely installed and functional.

### Signature(s) of Acknowledgement



**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP**

FACILITY NAME <b>HOLIDAY INN VICTORVILLE</b>	DATE <b>4/14/2015</b>
LOCATION <b>15494 PALMDALE RD, VICTORVILLE, CA 92392</b>	INSPECTOR <b>Bennetta Betbadal</b>

NAME:  
TITLE:

**Total # of Images: 0**