



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME DEL SOL HOA		DATE 7/14/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 2766 DEL SOL CT, CHINO HILLS, CA 91709			INSPECTOR Casey Salazar	
MAILING ADDRESS 17731 IRVINE BLVD STE 212, TUSTIN CA 92780			IDENTIFIER: Spa	
TIME IN 3:01 PM	TIME OUT 4:01 PM	FACILITY ID FA0000980	RELATED ID PR0015820	PE 3623
			SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED	

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

97

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$ 4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

Ideal
In Compliance
Not in Compliance



temperature (°F)	101.0
observed flow (gpm)	56
required flow (gpm)	48
volume (gal)	1,434
area (sq ft)	63
occupancy	6

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K504 Water Quality – Non-Critical – Disinfectant level low

POINTS
1

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC - 65529

Inspector Comments: Observed free chlorine levels at 0.39 ppm. Maintain free chlorine between 2-10 ppm.

Violation Description: The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

36K508 Water Quality – Non-Critical – Water pH 7.2 to 7.8

POINTS
1

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC - 65530

Inspector Comments: Observed pH at 7.9. Maintain pH between 7.2-7.8.

Violation Description: The pool operator shall maintain public pool water at pH 7.2 to 7.8.

36K538 Enclosure – Non-Critical – Fencing/Enclosure

POINTS
1

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR - 3119B

Inspector Comments: Observed bottom rail of fencing to be rusted through in various areas around enclosure. Observed one metal rail rusted and bent to provide a 5 inch opening. Repair/replace fencing within 2 weeks.

Corrective action: Rail was zip-tied to close opening to 4 inches.

Violation Description: The enclosure shall have a minimum effective perpendicular height of 5 feet. Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a 4-inch (102 mm) diameter sphere. The enclosure shall be designed and constructed so that it cannot be readily climbed by small children. Chain link may be used, provided that the openings are not greater than 1¼ inches (44 mm) measured horizontally.

Overall Inspection Comments

Spa inspection conducted



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME DEL SOL HOA	DATE 7/14/2015
LOCATION 2766 DEL SOL CT, CHINO HILLS, CA 91709	INSPECTOR Casey Salazar

Signature(s) of Acknowledgement

A handwritten signature in blue ink that reads "SNA".

NAME: Signature not available

TITLE:

Total # of Images: 0