






Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME MADISON PARK ALTA LOMA			DATE 7/30/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 7/31/2015
LOCATION 10757 LEMON AV, RANCHO CUCAMONGA, CA 91701				INSPECTOR Dior Porter	
MAILING ADDRESS 800 IRON POINT RD, FOLSOM CA 95630				IDENTIFIER: Back Spa	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT				SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 4:11 PM	TIME OUT 4:26 PM	FACILITY ID FA0004884	RELATED ID PR0015432	PE 3623	RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

No Violations Cited

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
 TITLE:

Total # of Images: 0