



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>NORTHWOOD HOA</b>		REINSPECTION DATE <b>Not Specified</b>		INSPECTOR <b>Maria Gomez-Casilla</b>	DATE <b>9/21/2016</b>
LOCATION <b>5984 RIVERWOOD RD, RANCHO CUCAMONGA, CA 93710</b>				PERMIT EXPIRATION <b>5/31/2017</b>	IDENTIFIER: Spa
TIME IN <b>2:36 PM</b>	TIME OUT <b>2:55 PM</b>	FACILITY ID <b>FA0005243</b>	RELATED ID <b>PR0015118</b>	PE <b>3623</b>	SERVICE: 001 - INSPECTION - ROUTINE
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE
					ACTION: 01 - NO FURTHER ACTION REQUIRED

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**


Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

**99**  
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	101.0
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	226
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K548 Equipment - General Requirements - System Description**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observe missing air lock device valve and weir gate from the skimmer.  Provide air lock device valve and weir gate.
	Not In Compliance	
	Violation Reference - CCR 24 - 3123B.1	

**Violation Description:** Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The system shall consist of pumps, filters, chemical feeders, skimmers or perimeter overflow systems, valves, pipes, connections, fittings and appurtenances.

**Overall Inspection Comments**

Note: Access to the pump room was unavailable at this time. Cannot determine if additional requirements are being met regarding records, GFCI, pool test kit, gauges, flow meter, leaks, and overall maintenance of pump equipment.

**Signature(s) of Acknowledgement**

SNA

NAME: Signature not available  
TITLE:

Total # of Images: 0