




Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME COLONY HIGH SCHOOL			DATE 8/24/2015	REINSPECTION DATE Next Routine	PERMIT EXPIRATION
LOCATION 3850 E RIVERSIDE DR, ONTARIO, CA 91761			INSPECTOR Veronica Martinez		
MAILING ADDRESS 211 W 5TH ST, ONTARIO CA 91761			IDENTIFIER: Pool		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION		
TIME IN 10:00 AM	TIME OUT 10:41 AM	FACILITY ID FA0010981	RELATED ID PR0016665	PE 3603	RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN

RECREATIONAL HEALTH - Public School Pool / Spa

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	1,485
volume (gal)	528,250
area (sq ft)	8,399
occupancy	419

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified
	Not In Compliance
	Violation Reference - HSC

Inspector Comments: The pool may reopen.

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified
	Not In Compliance
	Violation Reference - HSC

Inspector Comments: A reinspection was conducted today in regard to a pool closure dur to high free chlorine levels observed during the last routine inspection.

Upon inspection, observed free chlorine residual measuring 4.39 ppm with a pH of 7.2. The pool may reopen

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Brice Sunderland
 TITLE:

Total # of Images: 0