



**Public Health**  
**Environmental Health Services**




www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME HAMPTON INN & SUITES			DATE 7/15/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 4/30/2016
LOCATION 250 N 9TH ST, COLTON, CA 92324				INSPECTOR John Babalola	
MAILING ADDRESS 105 DECKER CT STE 500, IRVING TX 75062			<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT IDENTIFIER: Spa SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED		
TIME IN 1:53 PM	TIME OUT 2:16 PM	FACILITY ID FA0008659	RELATED ID PR0014088	PE 3623	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	100.0
observed flow (gpm)	50
required flow (gpm)	60
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K994 Reinspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

**Inspector Comments:** All violations noted on the inspection report of 7-2-15 have been corrected.

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME: ruben castro  
 TITLE: chief engeneer

Total # of Images: 0