



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | | | | |
|--|---------------------|--------------------------|--|--------------------------------|
| FACILITY NAME MEADOWOOD VILLAGE | | DATE 7/14/2015 | REINSPECTION DATE Not Specified | PERMIT EXPIRATION 9/30/2015 |
| LOCATION 10153 SHADY OAKS DR, RANCHO CUCAMONGA, CA 91730 | | | INSPECTOR Nick Thalasinios | |
| MAILING ADDRESS 1235 E FRANCIS ST STE E, ONTARIO CA 91761 | | | IDENTIFIER: Spa | |
| TIME IN 4:45 PM | TIME OUT 5:25 PM | FACILITY ID FA0006124 | RELATED ID PR0016916 | PE 3623 |
| | | | SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED | |

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

98

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$ 4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.

| |
|-------------------|
| Ideal |
| In Compliance |
| Not in Compliance |



| | |
|---------------------|-------|
| temperature (°F) | 102.3 |
| observed flow (gpm) | 75 |
| required flow (gpm) | 60 |
| volume (gal) | 1,798 |
| area (sq ft) | 80 |
| occupancy | 8 |

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K528 Safety – Safety equipment

POINTS
1

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC - 65540

Inspector Comments: Observed the life ring lacks a throw rope; The pool operator shall ensure that an attached throw rope with a minimum 3/16-inch diameter is provided and maintained readily visible and available for use at the public pool at all times. The throw rope shall be of sufficient length to span the maximum width of the public pool and shall be stored in such a way as to prevent kinking or fouling.

Violation Description: Except for spray grounds without standing water, the pool operator shall ensure that the following safety and first aid equipment is provided and maintained readily visible and available for use at the public pool at all times:

- (1) A 17-inch-minimum (exterior diameter) life ring with an attached throw rope with a minimum 3/16-inch diameter. The throw rope shall be of sufficient length to span the maximum width of the public pool and shall be stored in such a way as to prevent kinking or fouling.
 - (2) A 12-foot-minimum fixed-length rescue pole with a permanently attached body hook. For spas, the length of the rescue pole shall be of sufficient length to effectuate rescue.
- For public pools that exceed 75 feet in length or 50 feet in width, the pool operator shall provide a rescue pole and a life ring on at least two opposing sides of the public pool at centralized locations.

For public pools with lifeguard personnel on duty, the pool operator of each public pool area shall have the following additional safety equipment:

- (1) A Red Cross 10-Person Industrial First Aid Kit or the equivalent.
- (2) An operating telephone.
- (3) A backboard and head immobilizer.

36K587 Ancillary - Drinking Fountains Required

POINTS
1

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - CCR 24 - 3117B

Inspector Comments: Observed no jet drinking fountain; One guarded jet drinking fountain shall be provided.

Violation Description: One guarded jet drinking fountain shall be provided for the first 250 pool users and an additional fountain shall be provided for each additional 200 pool users or fraction thereof.

Overall Inspection Comments

Spa Pool

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

| | |
|---|------------------------------|
| FACILITY NAME MEADOWOOD VILLAGE | DATE 7/14/2015 |
| LOCATION 10153 SHADY OAKS DR, RANCHO CUCAMONGA, CA 91730 | INSPECTOR Nick Thalasinis |

NAME:
TITLE:

Total # of Images: 0