



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME FERNROCK ESTATES		DATE 6/28/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 5/31/2016
LOCATION 872 SIERRA VISTA DR, TWIN PEAKS, CA 92391			INSPECTOR Sumedha Singh	
MAILING ADDRESS 1420 N CLAREMONT BL STE 205-D, CLAREMONT CA 91711			IDENTIFIER: Pool	
TIME IN 11:54 AM			SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME OUT 12:09 PM			RESULT: 00 - NOT APPLICABLE	
FACILITY ID FA0001438			ACTION: 00 - NOT APPLICABLE	
RELATED ID PR0015696			PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Address was unable to be located. Inspection will be conducted on a later date.
	Not In Compliance	
	Violation Reference - HSC	

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0