






**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>SUNRISE PASS ESTATES</b>		DATE <b>7/31/2015</b>	REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>7/31/2015</b>
LOCATION <b>1000 WINDY PASS RD, BARSTOW, CA 92311</b>			INSPECTOR <b>Michelle Saltis</b>	
MAILING ADDRESS <b>22880 SAVI RANCH PKWY, YORBA LINDA CA 92887</b>			IDENTIFIER: Spa	
TIME IN <b>2:07 PM</b>	TIME OUT <b>2:28 PM</b>	FACILITY ID <b>FA0007236</b>	RELATED ID <b>PR0013827</b>	PE <b>3623</b>
			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

<b>Ideal</b>
<b>In Compliance</b>
<b>Not in Compliance</b>



temperature (°F)	102.0
observed flow (gpm)	No Data
required flow (gpm)	67
volume (gal)	2,000
area (sq ft)	95
occupancy	9

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Spa permit is hereby reinstated. Facility may reopen spa.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> A reinspection was conducted today, 7/31/15, to follow up on spa chemical readings and to ensure fencing is repaired.  Observe fence repaired and in good working condition. Observed pH of spa water measuring at 7.00. Maintain pH between 7.2-7.8. Observed free chlorine measuring at 2.02. Maintain free chlorine in spa water between 3-10ppm. Observed Cyanuric acid measuring at 90.4.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**36K504 Water Quality – Non-Critical – Disinfectant level low**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Maintain free chlorine in spa water between 3-10ppm.  Observed spa water free chlorine measuring at 2.02ppm.
	Not In Compliance	
	Violation Reference - HSC - 65529	

**Violation Description:** The minimum concentration of disinfectant residual in public pools shall be 1.0 ppm free-chlorine without cyanuric acid or 2.0 ppm free-chlorine with cyanuric acid. The minimum concentration of disinfectant residual in public spas, wading pools, and spray grounds shall be 3.0 ppm free-chlorine. The maximum concentration of disinfectant residual shall be 10.0 ppm free-chlorine.

The minimum concentration of bromine residual in public pools shall be 2.0 ppm. The minimum concentration of bromine residual in public spas, wading pools, and spray grounds shall be 4.0 ppm.

**36K508 Water Quality – Non-Critical – Water pH 7.2 to 7.8**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed pH of spa water measuring at 7.00.  Maintain pH between 7.2-7.8.
	Not In Compliance	
	Violation Reference - HSC - 65530	

**Violation Description:** The pool operator shall maintain public pool water at pH 7.2 to 7.8.

**Overall Inspection Comments**



**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>SUNRISE PASS ESTATES</b>	DATE <b>7/31/2015</b>
LOCATION <b>1000 WINDY PASS RD, BARSTOW, CA 92311</b>	INSPECTOR <b>Michelle Saltis</b>

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME: nelson yaris  
TITLE: maintenance

Total # of Images: 0