





Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RANCHO MONTE VISTA MOBILEHOME PARK			DATE 7/23/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2015
LOCATION 15050 MONTE VISTA AV, CHINO HILLS, CA 91710				INSPECTOR Casey Salazar	
MAILING ADDRESS 1801 E EDINGER AV STE 230, SANTA ANA CA 92705				IDENTIFIER: Pool	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT				SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME IN 11:14 AM	TIME OUT 11:24 AM	FACILITY ID FA0006998	RELATED ID PR0014036	PE 3620	RESULT: 00 - NOT APPLICABLE
ACTION: 00 - NOT APPLICABLE					

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	197
volume (gal)	70,860
area (sq ft)	1,552
occupancy	76

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS
NA

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC

Inspector Comments: Observed sign posted at gate indicating pool is closed for maintenance. Per office personnel, main drain covers are being replaced. Maintenance is expected to be done by the end of the week.

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

Attempted inspection

Signature(s) of Acknowledgement

NAME:
 TITLE:
 Total # of Images: 0