



Public Health

Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME ALTA LOMA HIGH SCHOOL		DATE 8/17/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701			INSPECTOR Tin Nguyen	
MAILING ADDRESS 276 N SECOND AVE UPLAND, CA 91786			IDENTIFIER: None	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 126 - PLAN CHECK FIELD INSPECTION	
TIME IN 1:45 PM	TIME OUT 3:09 PM	FACILITY ID FA0006436	RELATED ID SR0065247	PE 3712
			RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU	
			ACTION: 03 - REINSPECTION REQUIRED	

RECREATIONAL HEALTH PLAN CHECK - PInCk Pool New 1,000-Up SqFt

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K983 Plans - Construction

Compliance Date: Not Specified

Inspector Comments: Facility hereby approved to open.

Not In Compliance

Reference - HSC

Description: Construction inspection to verify equipment listed on plans.

37K067 Enclosure - General - Climb

Compliance Date: Not Specified

Inspector Comments: Observed five gates around pool with horizontal bars that were climbable. Measured distance between horizontal bars less than four feet. Provide barrier to gates to prevent possible climbing.

Not In Compliance

Reference - CCR 24 - 3118B.3

Description: The enclosure shall be designed and constructed so that it cannot be readily climbed by small children. Horizontal and diagonal member designs, which might serve as a ladder for small children, are prohibited. Horizontal members shall be spaced at least 48 inches apart.

37K246 Safety - General - Sign

Compliance Date: Not Specified

Inspector Comments: Observed "keep gate closed" missing on all gates around pool. Provide "keep gate closed" sign on all pool gates.
Observed phone number for nearest emergency facility missing. Provide phone number to nearest emergency facility other than "911" (e.g. nearest police, fire, or hospital).
Observed directional arrows missing on directional arrows. Indicate direction of flow (e.g. arrows) on recirculation pipes.

Not In Compliance

Reference - CCR 22 - 65539

Description: Post safety signs and supply safety equipment so that they will be clearly visible and readily available to the pool.

37K300 Water Quality - Chlorine

Compliance Date: Not Specified

Inspector Comments: Observed free chlorine measuring 0.66 ppm. Maintain minimum free chlorine concentration of 2.0 ppm if cyanuric acid is used and 1.0 ppm without cyanuric acid.

Not In Compliance

Reference - CCR 22 - 65529 (a)

Description: Maintain a minimum of 1.5 ppm of free chlorine when pool is open for use. (1.0 ppm without cyanuric acid).

Overall Inspection Comments

Reinspection needed to verify hot water at shower stalls and completion of restrooms located outside of pool area. Restrooms must be completed within 2 weeks. Call 800-442-2283 for reinspection.

The next reinspection will be billed at the hourly rate (\$245 hourly at a half-hour minimum).

Observed flow rate: 1442 gallons per minute (gpm)

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME ALTA LOMA HIGH SCHOOL	DATE 8/17/2015
LOCATION 8880 BASELINE RD, RANCHO CUCAMONGA, CA 91701	INSPECTOR Tin Nguyen

A handwritten signature in blue ink that reads "Lanette Barris".

NAME: Lanette Barris
TITLE: Project Administrator

Total # of Images: 0