



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR		REINSPECTION DATE Not Specified		INSPECTOR Anies Kondoker	DATE 10/2/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404				PERMIT EXPIRATION	IDENTIFIER: None
TIME IN 8:17 AM	TIME OUT 8:56 AM	FACILITY ID FA0008381	RELATED ID CO0052293	PE 3620	SERVICE: 004 - COMPLAINT - INITIAL RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K993 Re-Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: _____
	Not In Compliance	
	Violation Reference - HSC	

Description: Billable re-reinspection conducted at the time to determine compliance from prior inspection.

36K999 Complaint Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: _____
	Not In Compliance	
	Violation Reference - HSC	

Description: A complaint report has been received by Environmental Health.

Overall Inspection Comments

This visit is a charged inspection. Andrew, a manager stated on 9/29/15 that a pool guy would treat the pool and spa to be in good condition and meet all required codes.

Health dept received another complaint stating that the pool and spa were green.

Observed pool water to be dark green with accumulation of floating debris and observed spa water to be green. Pool gates are padlocked.

The pool and spa water must be drained or must be brought up to good clarity condition as required by codes by Monday, 10/5/15.

Another charged inspection will be conducted on or after 10/6/15 to determine compliance. Non-compliance will result in an office hearing or further legal action.



Public Health
Environmental Health Services

www.SBCounty.gov
www.SBCounty.gov/dph/dehs

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME EUREKA MANOR	DATE 10/2/2015
LOCATION 1525 E EUREKA ST, SAN BERNARDINO, CA 92404	INSPECTOR Anies Kondoker

Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0