




**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME HAMPTON COURT APARTMENTS			DATE 9/2/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 1452 E PUMALO ST, SAN BERNARDINO, CA 92404			INSPECTOR Anies Kondoker		
MAILING ADDRESS 136 E HIGHLAND AV, SAN BERNARDINO CA 92404			IDENTIFIER: Pool		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 008 - INSPECTION - ATTEMPTED		
TIME IN 8:16 AM	TIME OUT 8:25 AM	FACILITY ID FA0008290	RELATED ID PR0015694	PE 3620	RESULT: 00 - NOT APPLICABLE
					ACTION: 00 - NOT APPLICABLE

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	40
volume (gal)	14,400
area (sq ft)	512
occupancy	25

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K996 Attempted Inspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
 Not In Compliance  
 Violation Reference - HSC

Inspector Comments: \_\_\_\_\_

**Description:** An inspection was attempted today. Another inspection will be attempted at a later date.

**Overall Inspection Comments**

No access to the pool enclosure.  
 Manager was not on site.

**Signature(s) of Acknowledgement**

NAME:  
 TITLE:  
 Total # of Images: 0