



**Public Health**  
Environmental Health Services



www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME ALTA LAGUNA MHP		DATE 5/14/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2015
LOCATION 10210 BASELINE RD, RANCHO CUCAMONGA, CA 91701			INSPECTOR Dior Porter	
MAILING ADDRESS 10210 BASELINE RD, RANCHO CUCAMONGA, CA 91701			IDENTIFIER: Spa	
<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME IN 9:09 AM	TIME OUT 9:19 AM	FACILITY ID FA0007247	RELATED ID PR0013961	PE 3623
RESULT: 00 - NOT APPLICABLE				
ACTION: 00 - NOT APPLICABLE				

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

<b>Ideal</b>
<b>In Compliance</b>
<b>Not in Compliance</b>



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K996 Attempted Inspection**

<b>POINTS</b>  <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed caution tape surrounding the spa. According to manager the spa is down for pump repair and heater repair. Ensure all parts are replaced like for like or contact the Plan Check Program of Environmental Health to inquire of approved equipment. 800-442-3383.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** An inspection was attempted today. Another inspection will be attempted at a later date.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0