



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME LA FITNESS				REINSPECTION DATE Not Specified	INSPECTOR Karen Vu	DATE 6/9/2016
LOCATION 9385 MONTE VISTA RD, MONTCLAIR, CA 91763				PERMIT EXPIRATION 11/30/2015	IDENTIFIER: Pool SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
TIME IN 9:30 AM	TIME OUT 9:45 AM	FACILITY ID FA0008507	RELATED ID PR0014483	PE 3620		



RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	150
volume (gal)	54,000
area (sq ft)	1,800
occupancy	90

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

No Violations Cited

Overall Inspection Comments

During the last routine inspection, the under water light fixture was loose.

Observed under water light fixture to be fixed.

The pool is now open and there is no need for an additional inspection at this time.

Signature(s) of Acknowledgement

NAME: Rafa Serfaty
TITLE:

Total # of Images: 0