



**Public Health**  
Environmental Health Services

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

|   |                      |                          |  |                                |
|---|----------------------|--------------------------|--|--------------------------------|
| FACILITY NAME<br><b>RECHE CANYON APARTMENTS</b>           |                      | DATE<br>4/16/2015        | REINSPECTION DATE<br>Not Specified               | PERMIT EXPIRATION<br>8/31/2015 |
| LOCATION<br>1333 RECHE CANYON RD, COLTON, CA 92324        |                      |                          | INSPECTOR<br>John Babalola                       |                                |
| MAILING ADDRESS<br>1333 RECHE CANYON RD, COLTON, CA 92324 |                      |                          | IDENTIFIER: Pool                                 |                                |
|   |                      |                          | SERVICE: 001 - INSPECTION - ROUTINE              |                                |
| TIME IN<br>10:57 AM                                       | TIME OUT<br>11:53 AM | FACILITY ID<br>FA0006088 | RELATED ID<br>PR0013671                          | PE<br>3620                     |
|   |                      |                          | RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE |                                |
|   |                      |                          | ACTION: 01 - NO FURTHER ACTION REQUIRED          |                                |

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked.

**96**

SCORE

Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$61.25 per 15 minutes with a minimum time of 30 minutes, and a minimum charge of \$122.50.

|                   |
|-------------------|
| Ideal             |
| In Compliance     |
| Not in Compliance |



|                     |         |
|---------------------|---------|
| temperature (°F)    | No Data |
| observed flow (gpm) | No Data |
| required flow (gpm) | 140     |
| volume (gal)        | No Data |
| area (sq ft)        | No Data |
| occupancy           | 18      |

**36K444 Equipment - Recirculation Pump/Filter/Separation Tank**

|   |                                |   |
|---|--------------------------------|---|
| <b>POINTS</b><br><b>2</b>                       | Compliance Date: Not Specified | <b>Inspector Comments:</b> No flow direction labels observed in the equipment room. Provide the labels. |
|   | Not In Compliance              |   |
| Violation Reference - HSC - 3120B, 3132B, 3141B |                                |   |

**Violation Description:** Each pool shall be provided with a separate recirculation system designed for the continuous recirculation, filtration and disinfection of the pool water. The pumps, filters and all related parts of the pool water purification system shall be kept in operation whenever the pool is available for use. All parts of the pool and related pool facilities and equipment shall be maintained in good repair.

The backwash from a diatomaceous earth filter shall discharge into a separation tank. The wastewater from the separation tank shall discharge into a sanitary sewer or other disposal system acceptable to the local wastewater agency.

The direction of flow for the recirculation equipment shall be labeled clearly with directional symbols such as arrows on all piping in the equipment area.

**36K472 Access - Steps - Handrails - Diving Area**

|  |                                |  |
|--|--------------------------------|--|
| <b>POINTS</b><br><b>2</b>                | Compliance Date: Not Specified | <b>Inspector Comments:</b> Secure the unstable hand rails. |
|  | Not In Compliance              |  |
| Violation Reference - CCR - 3111B, 3113B |                                |  |

**Violation Description:** Stairs shall be provided in the shallowest portion of a pool. Ladders shall be corrosion resistant and shall be equipped with slip resistant tread surfaces. Ladders shall be rigidly installed. Hand rails shall be provided at the top of both sides of each ladder and recessed steps and shall extend over the coping or edge of the deck. Diving boards and platforms shall be anchored to the pool deck, constructed of corrosion resistant material, designed and constructed to be easily cleanable and finished with a durable slip resistant material.

**Overall Inspection Comments**

Observed pH=7.2, chlorine=5.7, cyanuric acid=60, flow rate=60

**Signature(s) of Acknowledgement**

NAME: antonio ramos  
TITLE: maintenance supervisor

Total # of Images: 0