



**Public Health**  
**Environmental Health Services**




www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME AMADOR ON ROUTE 66		DATE 7/28/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 8/31/2014
LOCATION 8090 CORNWALL, RANCHO CUCAMONGA, CA 91739			INSPECTOR Nick Thalasinis	
MAILING ADDRESS 1760 CALIFORNIA AV STE 101, CORONA CA 92881			IDENTIFIER: Spa	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 3:50 PM	TIME OUT 4:10 PM	FACILITY ID FA0015706	RELATED ID PR0020872	PE 3623
			RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU	
			ACTION: 03 - REINSPECTION REQUIRED	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	28
volume (gal)	859
area (sq ft)	50
occupancy	5

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K538 Enclosure – Non-Critical – Fencing/Enclosure**

<b>POINTS</b>  <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed eight (8) climbable trees along the fence; No planters or other structures that can be climbed shall be permitted within five (5) feet (1524 mm) of the outside of the pool enclosure or within a five (5) foot (1524 mm) arc.
	Not In Compliance	
	Violation Reference - CCR - 3119B	

**Violation Description:** The enclosure shall have a minimum effective perpendicular height of 5 feet. Openings, holes or gaps in the enclosure, doors and/or gates shall not allow the passage of a 4-inch (102 mm) diameter sphere. The enclosure shall be designed and constructed so that it cannot be readily climbed by small children. Chain link may be used, provided that the openings are not greater than 1¼ inches (44 mm) measured horizontally.

**Overall Inspection Comments**

I spoke to the property management company today, and received a correct email and mailing address for them. The facility has one (1) week to remove the trees rom the outside of the pool fence.

**Signature(s) of Acknowledgement**

NAME:  
 TITLE:  
 Total # of Images: 0