



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME MULBERRY PLACE		DATE 7/7/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 8/31/2015
LOCATION ARROW ROUTE / VINEYARD , RANCHO CUCAMONGA, CA 91730			INSPECTOR Shannon Johnson	
MAILING ADDRESS PO BOX 5022, UPLAND CA 91785			IDENTIFIER: Pool	
TIME IN 8:56 AM			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME OUT 9:05 AM			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID FA0006099			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
RELATED ID PR0014903			PE 3620	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	45
volume (gal)	22,000
area (sq ft)	740
occupancy	37

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: The pH and free chlorine within this pool water were observed to be in compliance at this time.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: During the routine inspection conducted on 7-6-15, then pH and free chlorine level of the pool water was measured and observed to be out of compliance.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

Correct any other noted violations from last routine inspection report.

Signature(s) of Acknowledgement

NSC

NAME:
TITLE:
Total # of Images: 0