



**Public Health**  
**Environmental Health Services**


www.SBCounty.gov

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME SUPER 8 MOTEL			DATE 8/18/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 2/28/2016
LOCATION 170 COOLWATER LN, BARSTOW, CA 92311			INSPECTOR Michelle Saltis		
MAILING ADDRESS 170 COOLWATER LN, BARSTOW CA 92311			IDENTIFIER: Pool		
TIME IN 1:03 PM			RELATED ID PR0014888	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME OUT 1:25 PM			PE 3620	RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
FACILITY ID FA0006125			ACTION: 01 - NO FURTHER ACTION REQUIRED		

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	50
volume (gal)	18,200
area (sq ft)	600
occupancy	30

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> A reinspection was conducted to follow up on compliance of the pool fencing.  Observed pool fencing in good condition and section that was missing is now repaired.  Observed light algae build up on side walls in pool. Clean and maintain on a routine basis.
	Not In Compliance Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**36K572 Maintenance – Pool shell cleanliness; slime and algae**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed light algae build up on side walls in pool.  Clean and maintain on a routine basis.
	Not In Compliance Violation Reference - HSC - 65533	

**Violation Description:** (a) The pool operator shall maintain clean pool water while the public pool is in use. The pool operator shall not allow debris, including, but not limited to, floating scum, sputum, trash, or leaves, to accumulate in the public pool. The pool operator shall ensure that water levels are maintained and operated to remove such material continuously through the pool skimming system in accordance with section 3136B, Title 24, California Code of Regulations.

(b) The pool operator shall clean the bottom, sides, and other surfaces of the public pool as often as necessary to keep the bottom, sides, and public pool surfaces clean and free of slime and algae.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME: mihir dace  
 TITLE: general manager

Total # of Images: 0