



**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME EDGEHILL VILLAGE HOA		DATE 7/27/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 6/30/2016
LOCATION 1400 EDGEHILL RD, SAN BERNARDINO, CA 92405			INSPECTOR Yvette Velasco	
MAILING ADDRESS PO BOX 7621, REDLANDS CA 92375			IDENTIFIER: Spa	
TIME IN 10:32 AM			SERVICE: 001 - INSPECTION - ROUTINE	
TIME OUT 10:48 AM			RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE	
FACILITY ID FA0008907			ACTION: 01 - NO FURTHER ACTION REQUIRED	
RELATED ID PR0014181			PE 3623	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.



**98**

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	102.0
observed flow (gpm)	50
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:  
 1. Meet the latest ANSI/APSP-16 performance standard  
 2. Be rated for the maximum designed flow-rate of the pump  
 Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K546 Equipment – Non-Critical - Water treatment system operation**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed one missing weir gate and one missing float assembly.
	Not In Compliance	
	Violation Reference - HSC - 65525	Ensure to repair/replace the weir gate and float assembly as soon as possible.

**Violation Description:** The pool operator shall operate pumps, filters, disinfectant and chemical feeders, flow indicators, gauges, recirculation systems, disinfection systems, and all parts of the water treatment system whenever the public pool is available for use, and at such additional times and periods as may be necessary to maintain clean pool water, clear pool water, and the disinfection standards required in section 65529 [Health and Safety Code].

**36K597 Construction - Pool shell tiles and surface**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Observed the spa shell chipping.
	Not In Compliance	
	Violation Reference - CCR - 3108B	Ensure to repair the pool shell as soon as possible.

**Violation Description:** The finished pool shell shall be lined with a smooth waterproof interior finish that will withstand repeated brushing, scrubbing and cleaning procedures. The interior pool finish shall completely line the pool to the tile lines, coping, or cantilevered deck.

- The finish color shall be white except for the following which shall be of contrasting color:
- Lane and other required pool markings described in Section 3110B of the California Code of Regulations; and
  - The top surface edges of benches in spa pools; and
  - The edge of pool steps; and
  - Tiles installed at the waterline; and
  - Tiles installed at the 4 1/2-foot (1372 mm) depth line.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**



**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME EDGEHILL VILLAGE HOA	DATE 7/27/2015
LOCATION 1400 EDGEHILL RD, SAN BERNARDINO, CA 92405	INSPECTOR Yvette Velasco

NAME:  
TITLE:

Total # of Images: 0