



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME ETIWANDA HIGH SCHOOL			REINSPECTION DATE Next Routine	INSPECTOR Dior Porter	DATE 9/30/2015
LOCATION 13500 VICTORIA ST, RANCHO CUCAMONGA, CA 91739			PERMIT EXPIRATION	IDENTIFIER: Diving Pool	
TIME IN 11:21 AM	TIME OUT 12:00 PM	FACILITY ID FA0006434	RELATED ID PR0014041	PE 3603	SERVICE: 001 - INSPECTION - ROUTINE
					RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE
					ACTION: 01 - NO FURTHER ACTION REQUIRED

RECREATIONAL HEALTH - Public School Pool / Spa



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

99
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	585
required flow (gpm)	66
volume (gal)	240,000
area (sq ft)	3,360
occupancy	168

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K582 Maintenance - Public pool site maintenance

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed chipped pool shell. Repair the shell so that it is smooth. Call plan check program at 800-442-2283 prior to repair.
	Not In Compliance	
	Violation Reference - HSC - 65535	

Violation Description: The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

Overall Inspection Comments

Note: unable to check gym/restroom area due to back up of sewage (area completely separate from the pool) Clean and sanitize all affected areas. Utilize restrooms near the activities center until repairs are made.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0