



Public Health
Environmental Health Services




www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME RAINTREE GARDENS			DATE 7/27/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 10/31/2014
LOCATION 18125 BELLFLOWER, ADELANTO, CA 92301			INSPECTOR Michelle Saltis		
MAILING ADDRESS 631 S OLIVE ST #860, LOS ANGELES CA 90014			IDENTIFIER: Pool		
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT			SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION		
TIME IN 11:11 AM	TIME OUT 11:43 AM	FACILITY ID FA0008631	RELATED ID PR0013611	PE 3620	RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU
ACTION: 03 - REINSPECTION REQUIRED					

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	78
volume (gal)	28,000
area (sq ft)	936
occupancy	46

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS
NA

Compliance Date: Not Specified
 Not In Compliance
 Violation Reference - HSC

Inspector Comments: A reinspection was conducted today, 7/27/15, to follow up on compliance of the facility fencing.

Observed fencing still loose and broken from the bottom of fence. Per manager on site, they have started the process of fixing the fence around the perimeter of the pool site and should be completed within 2 days. Per manager on site, facility is keeping pool closed until repairs are completed.

A charged re-inspection will be conducted to follow up on compliance of fencing within a week. Please contact Michelle Saltis or Environmental Health with any questions or concerns at 800-442-2283.

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

A charged re-inspection will be conducted to follow up on compliance of fencing within a week. Please contact Michelle Saltis or Environmental Health with any questions or concerns at 800-442-2283.

Signature(s) of Acknowledgement

NAME: luciana velazquez
 TITLE:

Total # of Images: 0