




Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME ALFA APARTMENTS		DATE 8/25/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 7/31/2016
LOCATION 2011 BORREGO, BARSTOW, CA 92311			INSPECTOR Michelle Saltis	
MAILING ADDRESS 31781 CAMINO CAPISTRANO STE 107, SAN JUAN CAPISTRANO 92675-3226		<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT IDENTIFIER: Pool SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVIC RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN		
TIME IN 2:08 PM	TIME OUT 2:32 PM	FACILITY ID FA0008383	RELATED ID PR0015253	PE 3620

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	61
volume (gal)	21,900
area (sq ft)	580
occupancy	29

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Facility is now in compliance with the gate to self close/latch. Pool permit is hereby reinstated and may reopen pool.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K993 Re-Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: A charged reinspection was conducted today to follow up on compliance to ensure the gate self closes/latches. Observed gate self latching/closing.
	Not In Compliance	
	Violation Reference - HSC	

Description: Billable re-reinspection conducted at the time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Raul S. Mena
 TITLE:

Total # of Images: 0