



Public Health

Environmental Health Services

RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REP

FACILITY NAME PARK VISTA		DATE 7/27/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION
LOCATION 1031 S PALMETTO AV, ONTARIO, CA 91762			INSPECTOR Bennetta Betbadal	
MAILING ADDRESS 675 W FOOTHILL BL CLAREMONT, CA 91711			IDENTIFIER: None	
<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT			SERVICE: 126 - PLAN CHECK FIELD INSPECTION	
TIME IN 9:56 AM	TIME OUT 10:43 AM	FACILITY ID FA0008422	RELATED ID SR0068930	PE 3716
			RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU	
			ACTION: 03 - REINSPECTION REQUIRED	

RECREATIONAL HEALTH PLAN CHECK - PInCk Pool Minor Remodel - all

IMPORTANT: Replacement of Suction Outlet Covers

Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

37K510 Plans - Preliminary Inspection

Compliance Date: Not Specified

Inspector Comments:

Not In Compliance

Reference - Reference Number - SBC Policy

Description: Preliminary inspection

Overall Inspection Comments

Continue as per approved plans.

Call for final inspection. Install depth markers and no diving tiles on the deck.

Signature(s) of Acknowledgement

NAME:

TITLE:

Total # of Images: 0