



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>SHADY TRAILS PARKHOUSE</b>		REINSPECTION DATE <b>Not Specified</b>		INSPECTOR <b>Yanan Zhu</b>	DATE <b>6/6/2016</b>
LOCATION <b>15800 S PARK LN, FONTANA, CA 92336</b>				PERMIT EXPIRATION <b>3/31/2017</b>	IDENTIFIER: Spa
TIME IN <b>10:30 AM</b>	TIME OUT <b>10:54 AM</b>	FACILITY ID <b>FA0014449</b>	RELATED ID <b>PR0019094</b>	PE <b>3623</b>	SERVICE: 001 - INSPECTION - ROUTINE RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 01 - NO FURTHER ACTION REQUIRED

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**




Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

**97**  
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	101.0
observed flow (gpm)	No Data
required flow (gpm)	148
volume (gal)	4,435
area (sq ft)	219
occupancy	21

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K574 Maintenance – Test kit**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified Not In Compliance Violation Reference - HSC - 65529	Inspector Comments: Observed Chemical test kit missing. Keep test kit on site for daily operation.
---------------------------	--	--

**Violation Description:** The pool operator shall maintain a test kit for measuring the disinfectant residual, pH, and, if used, cyanuric acid concentration at the public pool. This test kit shall be available for use by the pool operator and the enforcing agent at all times the public pool is in use. The chlorine or bromine test kit shall be the diethyl-p-phenylenediamine (DPD) type or otherwise be capable of testing free-halogen residual.

**36K582 Maintenance - Public pool site maintenance**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified Not In Compliance Violation Reference - HSC - 65535	Inspector Comments: Observed Flow Meter non-functioning. Maintain functioning flow meter, replace/repair.
---------------------------	--	---

**Violation Description:** The pool operator shall keep all parts of the public pool site well-maintained, including, but not limited to, the public pools, water treatment systems, ancillary facilities, signs, showers, toilets, dressing facilities, drinking fountains, diaper-changing stations, floors, walls, partitions, doors, and lockers.

**36K584 Maintenance - Operating procedures/Manufacturers' instructions**

<b>POINTS</b> <b>1</b>	Compliance Date: Not Specified Not In Compliance Violation Reference - HSC - 65521	Inspector Comments: Observed operating procedures and manufacturers instructions operating and maintenance instructions for mechanical and electrical equipment missing. Keep this documents on site.
---------------------------	--	---

**Violation Description:** The pool operator shall maintain pool operating procedures at the public pool site for use by the pool operator and for inspection by the enforcing agent.

The pool operator shall maintain manufacturers' instructions for the operation and maintenance for all mechanical and electrical equipment and water treatment systems at the public pool site for use by the pool operator and for inspection by the enforcing agent.

**Overall Inspection Comments**

No summary comments have been made for this inspection.



Public Health  
Environmental Health Services

[www.SBCounty.gov](http://www.SBCounty.gov)  
[www.SBCounty.gov/dph/dehs](http://www.SBCounty.gov/dph/dehs)

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME SHADY TRAILS PARKHOUSE	DATE 6/6/2016
LOCATION 15800 S PARK LN, FONTANA, CA 92336	INSPECTOR Yanan Zhu

**Signature(s) of Acknowledgement**

NAME: Rob This  
TITLE: General Manger

Total # of Images: 0