





**Public Health**  
**Environmental Health Services**

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>PARK VISTA</b>			DATE <b>8/11/2015</b>	REINSPECTION DATE <b>Not Specified</b>	PERMIT EXPIRATION <b>2/28/2016</b>
LOCATION <b>1031 S PALMETTO , ONTARIO, CA 91761</b>				INSPECTOR <b>Veronica Martinez</b>	
MAILING ADDRESS <b>PO BOX 5022, UPLAND CA 91785</b>			<input type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input checked="" type="checkbox"/> ACCOUNT IDENTIFIER: Lone Spa SERVICE: 008 - INSPECTION - ATTEMPTED RESULT: 00 - NOT APPLICABLE ACTION: 00 - NOT APPLICABLE		
TIME IN <b>11:29 AM</b>	TIME OUT <b>12:00 PM</b>	FACILITY ID <b>FA0008422</b>	RELATED ID <b>PR0013982</b>	PE <b>3623</b>	

**RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K996 Attempted Inspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> An inspection was attempted today. Access to facility unavailable at time of inspection.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** An inspection was attempted today. Another inspection will be attempted at a later date.

**Overall Inspection Comments**

Note: Magnetic key provided to department not working at time of inspection. Residents keys not functional at time of inspection as well. Management contacted.

Repair magnetic lock and provide working set of keys to Department of Environmental Health Services: 8575 Haven Avenue, Suite #130, Rancho Cucamonga, CA 91730-9105

Second notice.

**Signature(s) of Acknowledgement**

NAME:  
 TITLE:  
 Total # of Images: 0