



**Public Health**  
**Environmental Health Services**




[www.SBCounty.gov](http://www.SBCounty.gov)

**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME AVENTERRA II APARTMENTS			DATE 7/16/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 5/31/2016
LOCATION 16225 ARROW BL, FONTANA, CA 92335				INSPECTOR Isaac Gebreslassie	
MAILING ADDRESS 16225 ARROW BL, FONTANA, CA 92335				IDENTIFIER: Pool	
<input checked="" type="checkbox"/> FACILITY <input type="checkbox"/> OWNER <input type="checkbox"/> ACCOUNT				SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION	
TIME IN 9:29 AM	TIME OUT 9:55 AM	FACILITY ID FA0005410	RELATED ID PR0015970	PE 3620	RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED
					ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	107
volume (gal)	38,682
area (sq ft)	1,228
occupancy	35

**IMPORTANT: Replacement of Suction Outlet Covers**  
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Permit now reinstated. Pool may reopen for use.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Upon reinspection, observed that chlorine level now has been adjusted to approved level.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME: Shirlae  
 TITLE: property manager

Total # of Images: 0