



**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME				REINSPECTION DATE	INSPECTOR	DATE
724 San Antonio, ONTARIO, CA				Not Specified	Veronica Martinez	10/9/2015
TIME IN	TIME OUT	FACILITY ID	RELATED ID	PERMIT EXPIRATION	IDENTIFIER: None	
1:40 PM	2:49 PM	Not Specified	COMZJ5L3L	PE 3620	SERVICE: 004 - COMPLAINT - INITIAL RESULT: 05 - CORRECTIVE ACTION / FOLLOW UP REQU ACTION: 03 - REINSPECTION REQUIRED	




**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:  
1. Meet the latest ANSI/APSP-16 performance standard  
2. Be rated for the maximum designed flow-rate of the pump  
Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K999 Complaint Inspection**

**POINTS**  
**NA**

Compliance Date: Not Specified  
Not In Compliance  
Violation Reference - HSC

**Inspector Comments:** A complaint inspection was conducted today in regard to a complaint received by our office alleging the pool enclosure fencing is deteriorated and compromising safety of enclose.

Upon inspection, observed (4) four points of fencing with excessive rusting and vertical elements detached from bottom of frame.

Observed pool shell with algae bloom. Observed free available chlorine measuring 5.97 ppm with pH measuring 7.7.

Repair fencing within (10) ten days and maintain enclosure secure.

On site correction: observed fencing secured with wiring to prevent possible entry.

**Description:** A complaint report has been received by Environmental Health.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:

Total # of Images: 0