



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME ESTANCIA APARTMENT HOMES		DATE 5/28/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 1/31/2016
LOCATION 1720 E D ST, ONTARIO, CA 91764			INSPECTOR John Ramos	
MAILING ADDRESS 1720 E D ST, ONTARIO CA 91764			IDENTIFIER: Pool	
			SERVICE: 008 - INSPECTION - ATTEMPTED	
TIME IN 11:00 AM	TIME OUT 11:07 AM	FACILITY ID FA0005663	RELATED ID PR0015786	PE 3620
			RESULT: 00 - NOT APPLICABLE	
			ACTION: 00 - NOT APPLICABLE	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	45
volume (gal)	17,166
area (sq ft)	510
occupancy	25

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K996 Attempted Inspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Office closed, unable to access pool.
	Not In Compliance	
	Violation Reference - HSC	

Description: An inspection was attempted today. Another inspection will be attempted at a later date.

Overall Inspection Comments

Office closed, unable to access pool.

Signature(s) of Acknowledgement

NAME:
TITLE:

Total # of Images: 0