



RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME TERRACINA APARTMENT			REINSPECTION DATE Not Specified		INSPECTOR Veronica Martinez	DATE 10/16/2015
LOCATION 2800 E RIVERSIDE DR, ONTARIO, CA 91761			PERMIT EXPIRATION 1/31/2016		IDENTIFIER: Middle Lone Pool SERVICE: 001 - INSPECTION - ROUTINE RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED	
TIME IN 1:59 PM	TIME OUT 2:33 PM	FACILITY ID FA0004929	RELATED ID PR0015195	PE 3621		

RECREATIONAL HEALTH - Public Pool - Additional Pool at Facility



Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional inspection to be billed at the hourly rate as provided in the San Bernardino County Code, [Schedule of Fees](#).

100
SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	68
volume (gal)	25,000
area (sq ft)	800
occupancy	40

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

- Meet the latest ANSI/APSP-16 performance standard
- Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K994 Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: A reinspection was conducted today in regard to a non compliant facility enclosure observed during the last pool aid survey. According to manager, repair work to loose enclosure footing and SE access gate completed. Upon reinspection, observed enclosure in compliance with existing enclosure gates observed to be self-latching and self-closing.
	Not In Compliance	
	Violation Reference - HSC	

Description: Reinspection conducted at this time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME: Wendy Cole
TITLE:

Total # of Images: 0