






**RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT**

FACILITY NAME <b>PALM TERRACE VILLAS</b>			REINSPECTION DATE <b>Not Specified</b>		INSPECTOR <b>Sierra Clayborn</b>	DATE <b>9/18/2015</b>
LOCATION <b>625 E PALM , REDLANDS, CA 92374</b>			PERMIT EXPIRATION <b>6/30/2016</b>		IDENTIFIER: Pool	
TIME IN <b>10:00 AM</b>	TIME OUT <b>10:42 AM</b>	FACILITY ID <b>FA0008729</b>	RELATED ID <b>PR0014309</b>	PE <b>3620</b>	SERVICE: 003 - INSPECTION - FOLLOW UP INSPECTION RESULT: 03 - CORRECTIVE ACTION / NO FOLLOW UP RE ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	

**RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility**

<b>Ideal</b>
<b>In Compliance</b>
<b>Not in Compliance</b>



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	No Data
volume (gal)	No Data
area (sq ft)	No Data
occupancy	No Data

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**36K992 Permit Reinstatement**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> Pool permit reinstated and open for use.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** The health permit to operate is hereby reinstated and facility may open.

**36K994 Reinspection**

<b>POINTS</b> <b>NA</b>	Compliance Date: Not Specified	<b>Inspector Comments:</b> During routine inspection, free chlorine exceeded 10ppm. During reinspection, observed free chlorine at exactly 10.1ppm.  Maintain pool free chlorine between 2.0ppm and 10ppm when using cyanuric acid. *Recommended to maintain the free chlorine closer to 5ppm.
	Not In Compliance	
	Violation Reference - HSC	

**Description:** Reinspection conducted at this time to determine compliance from prior inspection.

**Overall Inspection Comments**

Please send a copy of pool enclosure and pump room key to Environmental Health Services at 385 N. Arrowhead Ave, San Bernardino.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0