



**RECREATIONAL HEALTH PLAN CHECK - OFFICIAL PLAN REVIEW REPORT**

FACILITY NAME <b>MOUNTAIN SPRINGS</b>			REINSPECTION DATE <b>Not Specified</b>	INSPECTOR <b>Bennetta Betbadal</b>	DATE <b>11/5/2015</b>
LOCATION <b>1413 SAN BERNARDINO RD, UPLAND, CA 91768</b>			PERMIT EXPIRATION	IDENTIFIER: None	
TIME IN <b>9:20 AM</b>	TIME OUT <b>9:30 AM</b>	FACILITY ID <b>FA0006123</b>	RELATED ID <b>SR0069660</b>	PE <b>3755</b>	SERVICE: 126 - PLAN CHECK FIELD INSPECTION RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED

**RECREATIONAL HEALTH PLAN CHECK - Plan Check Rec Health Consultation**

**IMPORTANT: Replacement of Suction Outlet Covers**  
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

**37K509 Plans - Final Inspection**

**Compliance Date:** Not Specified      **Inspector Comments:** Final inspection for SVRS pump added for office spa circulation pump.

**Not In Compliance**

**Reference - Reference Number - SBC Policy**

**Description:** Final inspection hereby gives facility approvals to open.

**Overall Inspection Comments**

No summary comments have been made for this inspection.

**Signature(s) of Acknowledgement**

NAME:  
TITLE:  
Total # of Images: 0