



Public Health
Environmental Health Services



www.SBCounty.gov

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME SUNRIDGE PINES APARTMENTS III		DATE 5/21/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2015
LOCATION 9920 19TH ST, RANCHO CUCAMONGA, CA 91701			INSPECTOR Dior Porter	
MAILING ADDRESS 10505 SORRENTO VALLEY RD UNIT 300, SAN DIEGO CA 92121			IDENTIFIER: Spa- West	
TIME IN 10:00 AM			SERVICE: 037 - POOL/SPA - BILLABLE INSPECTION SERVIC	
TIME OUT 10:15 AM			RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED	
FACILITY ID FA0004825			ACTION: 15 - PERMIT REINSTATED / FACILITY RE-OPEN	
RELATED ID PR0015214			PE 3623	

RECREATIONAL HEALTH - Public Pool - Additional Spa at Facility

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	59
volume (gal)	1,766
area (sq ft)	78
occupancy	7

IMPORTANT: Replacement of Suction Outlet Covers
Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:

1. Meet the latest ANSI/APSP-16 performance standard
2. Be rated for the maximum designed flow-rate of the pump

Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K992 Permit Reinstatement

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Measured 8.0ppm chlorine. Thank you! Permit reinstated.
	Not In Compliance	
	Violation Reference - HSC	

Description: The health permit to operate is hereby reinstated and facility may open.

36K993 Re-Reinspection

POINTS NA	Compliance Date: Not Specified	Inspector Comments: Re-reinspection to determine compliance for chlorine level. Measured 8.0ppm chlorine.
	Not In Compliance	
	Violation Reference - HSC	

Description: Billable re-reinspection conducted at the time to determine compliance from prior inspection.

Overall Inspection Comments

No summary comments have been made for this inspection.

Signature(s) of Acknowledgement

NAME:
TITLE:
Total # of Images: 0