



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME HIGHLAND PALMS HOA		DATE 9/2/2015	REINSPECTION DATE Not Specified	PERMIT EXPIRATION 12/31/2015
LOCATION 3582 20TH ST, SAN BERNARDINO, CA 92404			INSPECTOR Sierra Clayborn	
MAILING ADDRESS 1420 N CLAREMONT BL STE 205D, CLAREMONT CA 91711		IDENTIFIER: Pool		
TIME IN 3:11 PM		TIME OUT 3:29 PM	FACILITY ID FA0007287	RELATED ID PR0014666
		PE 3620	SERVICE: 001 - INSPECTION - ROUTINE RESULT: 01 - CORRECTIVE ACTION NOT REQUIRED ACTION: 01 - NO FURTHER ACTION REQUIRED	

RECREATIONAL HEALTH - Public Pool - Initial Pool at Facility

Based on an inspection this day, the items marked below identify the violation(s) in operation or facilities which must be corrected. Failure to correct listed violation(s) prior to the designated compliance date may necessitate an additional reinspection at a charge of \$4.08 per 1 minute with a minimum time of 30 minutes, and a minimum charge of \$122.50.



98

SCORE

Administrative Order to Show Cause (OSC): The Permittee has the right to a hearing if requested in writing within 15 calendar days of receipt of this notice, to show cause why the permit to operate should not be suspended or revoked; otherwise the right to a hearing shall be deemed waived.

See the following pages for the code sections and general requirements that correspond to each violation listed below.

Ideal
In Compliance
Not in Compliance



temperature (°F)	No Data
observed flow (gpm)	No Data
required flow (gpm)	69
volume (gal)	33,000
area (sq ft)	800
occupancy	40

IMPORTANT: Replacement of Suction Outlet Covers
 Suction Outlet covers (anti-entrapment covers over main drains and skimmer equalizer outlets) shall be replaced upon expiration. The expiration (in years) is stamped on the front of each cover, indicating the amount of time the cover is valid after installation. Each replacement cover shall:
 1. Meet the latest ANSI/APSP-16 performance standard
 2. Be rated for the maximum designed flow-rate of the pump
 Retain all records which indicate the make/model number of the replacement cover and date of installation. Records shall be made available to your inspector upon request.

36K516 Water Quality – Non-Critical – Water clarity

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed water clarity slightly poor, main drain still visible from deck. Maintain water clarity in good condition.
	Not In Compliance	
	Violation Reference - HSC - 65527	

Violation Description: The pool operator shall maintain clear pool water while the public pool is in use. The pool operator shall close the public pool if the bottom of the pool at the maximum depth is not clearly visible from the deck. The pool operator shall not reopen the public pool for use until the pool water is clean and clear, and the bottom of the pool at the maximum depth is clearly visible from the deck. If the bottom of the pool is not visible 48 hours following inspection and closure by the enforcing agent, the enforcing agent may order the pool drained.

36K588 Restrooms - Toilet facilities/Showers

POINTS 1	Compliance Date: Not Specified	Inspector Comments: Observed cobwebs and spiders in restrooms and showers. Observed toilet paper missing from both restrooms. Maintain restrooms clean and supplied.
	Not In Compliance	
	Violation Reference - CCR - 3116B	

Violation Description: Separate toilet facilities shall be provided for each sex. One toilet shall be provided for every 60 women or less and one toilet plus one urinal for every 75 men or less. One lavatory shall be provided for every 80 pool users.

Shower and dressing facilities shall be provided for users of a pool.

Overall Inspection Comments

Maintenance supervisor on site stated that pool is closed for the remainder of the season, pool covered by a large black tarp. Pool is serviced on a monthly basis.

Signature(s) of Acknowledgement



Public Health
Environmental Health Services

RECREATIONAL HEALTH - OFFICIAL INSPECTION REPORT

FACILITY NAME HIGHLAND PALMS HOA	DATE 9/2/2015
LOCATION 3582 20TH ST, SAN BERNARDINO, CA 92404	INSPECTOR Sierra Clayborn

NAME: Cory
TITLE: Maintenance Supervisor

Total # of Images: 0